

LIND SCHOOL

52nd and Camden Avenue North

1931

Miss A. C. Barse, Principal

Originally Erected	1920
Number of Class Rooms	10
Number of Special Rooms	0
Enrollment	344

LIND SCHOOL

The usual type of frame portable school

DETAILED REPORT

OCCUPANCY: Boiler Room, basement. Class Rooms, first.

CARE AND MAINTENANCE: Building in good repair, premises neat.

EGRESS FACILITIES: Fair, halls in rear addition partially blocked with tables and chairs, exit from office blocked by a desk.

COMMON HAZARDS: LIGHT -- All wiring in rigid conduit, in good condition. HEAT -- Hot water from boilers in wood metal lined room, not safely arranged.

SPECIAL HAZARDS: None.

EXPOSURES: None.

FIRST AID PROTECTION: None except a deficient number of chemical fire extinguishers.

PUBLIC PROTECTION: Poor, one conveniently located fire hydrant on 6 inch water main, one fire department over one and one-half miles, paved and unpaved streets intervening.

RECOMMENDATIONS

1. Install sufficient number of approved chemical fire extinguishers.
2. Erect a fireproof room for all heating boilers, until that is done protect breeching with asbestos lagging, (paint has blistered and fallen off metal siding from the heat).
3. Keep aisles clear by removing tables and chairs.
4. Remove desk in office which partially blocks outside exit.
5. Provide additional exit direct to outside from class room in southwest corner of building.

