

ALCOTT SCHOOL

St. Louis Avenue and W. 29th Street

1931

Miss Alfreda H. Voigt, Principal

Originally Erected	1921
Number of Class Rooms	2
Number of Special Rooms	0
Enrollment	66

ALCOTT SCHOOL

A small frame building containing only two class rooms. Egress facilities are good.

DETAILED REPORT

OCCUPANCY: This building contains no special features.

CARE AND MAINTENANCE: Building in good repair and cleanliness is good.

EGRESS FACILITIES: Each class room is provided with one exit door and an emergency exit exists through boiler room. Egress facilities are good except that exit doors are not equipped with panic bars and interior vestibule doors are not free swinging.

COMMON HAZARDS: LIGHT -- Electric, standard installation of open wiring. HEAT -- Hot water heating boiler located in attached frame addition. VENTILATION -- Through windows.

SPECIAL HAZARDS: None.

EXPOSURES: None.

FIRST AID PROTECTION: Chemical fire extinguisher protection adequate.

PUBLIC PROTECTION: A fairly good supply of water available from three nearby hydrants. Public fire alarm box one and one-half blocks distant. Nearest fire station one and one-half miles over paved and improved streets.

RECOMMENDATIONS

1. Provide panic bars on exit doors and make interior vestibule doors free swinging.

6" W. PIPE (DEAD ENDED)


6" W. PIPE == W. 29TH ST.

1/2 BLOCKS TO FIRE ALARM BOX
350' TO D.H.
250' TO D.H.

ALCOTT SCHOOL

MINNEAPOLIS, MINNESOTA

SCALE: 1 IN. = 50 FT.



ST. LOUIS AVE.

D.H.

6" W. PIPE

ERECTED: 1921.
CONDITION: Good.
HEIGHT: One story
AREA: 2,360 Sq. Ft.
WALLS: Frame.
FLOORS: Ordinary wood joisted.
ROOF: Ordinary wood joisted, metal and composition surfacing.
FLOOR OPENINGS: None.

